


0.004 in.



0.002 in.

The figures show partially healed micropores found on fracture faces of short-lived specimens taken from a 6 in. thick 7050-T7452 hand forging.

**Figure 19: Microporosity is sometimes found to be the failure-initiating microfeature in tests of smooth fatigue specimens taken from thick hand forgings.**