



1990 pedigree plate



Low porosity plate

Figure 9: Backscattered SEM images of constituent particles located in the hole bore of open hole fatigue specimens from the 1990 and low porosity 7050-T7451 thick plate variants.